Insured/Applicant Name:	Application / Policy #:						
Address Inspected:							
Actual Year Built: 1993	Date Inspected: 12/06/2023						
Minimum Photo Requirements							
☑ Dwelling: Each side ☑ Roof: Each slope ☑ Plumbing: Water heater, under cabinet plumbing/drains, exposed valves							
☑ Main electrical service panel with interior door label							
lacktriangle Electrical box with panel off							
☑ All hazards or deficiencies noted in this report							
A Florida-licensed inspector must complete, sign and date this form.							

Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.

Electrical System							
Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.							
Main Panel		Second Panel					
Type: ☑ Circuit breaker ☐ Fuse		Type: ☑ Circuit breaker ☐ Fuse					
Total Amps: $\underline{125/125/100}$ Is amperage sufficient for current usage? $\underline{\mathbf{M}}$ Yes \square No (explain)		Total Amps: $125/125/125$ Is amperage sufficient for current usage? \square Yes \square No (explain)					
is amperage sumdent for current usage? 🗷 res	□ No (explain)	is amperage sufficient i	or current usage? ☑ Yes ☐ No (explain)				
Indicate presence of any of the following:		<u> </u>					
☐ Cloth wiring							
☐ Active knob and tube							
☐ Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring):							
* If single strand (aluminum branch) wiring, provide details of all remediation. Separate documentation of all work must be provided.							
☐ Connections repair via COPALUM crimp							
☐ Connections repair via AlumiConn							
Hazards Present		☐ Exposed wiring					
☐ Blowing fuses		☐ Over fusing					
☐ Empty sockets		☐ Unsafe wiring					
□ Loose Wiring		☐ Improper breaker size					
☐ Tripping breakers		☐ Scorching					
☐ Improper grounding		☐ Other (explain)					
□Corrosion							
☐ Double taps							
General condition of the electrical system: ☑ Satisfactory ☐ Unsatisfactory (explain)							
Supplemental information							
Main Panel	Second Panel		Wiring Type				
Panel age: 30	Panel age: 30/30/3		☑ Copper ☑ NM, BX or Conduit				
Year last updated: 1993/2020	Year last updated: <u>'93/'93/'20</u>		INIVI, DA UI CUITUUIL				
Brand/Model: ITE, Square D	Brand/Model: Siemens, General Electric						

HVAC System					
Central AC: ☑ Yes ☐ No					
Central heat: ☑ Yes ☐ No					
If not central heat, indicate primary heat source and fuel type:					
Are the heating, ventilation and air conditioning systems in good working or	rder? ☑ Yes ☐ No (explain)				
Date of last HVAC servicing/inspection: 12/06/2023					
Hazards Present					
Wood burning stove or central gas fireplace not professionally installed?	Yes ☑No				
Space heater used as primary heat source? ☐ Yes ☑ No					
Is the source portable? ☐ Yes ☑ No					
Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? ☐ Yes ☑ No					
Supplemental Information					
Age of system:					
Year last updated: (Please attach photo(s) of HVAC equipment, including dated manufacturer's	s plate)				
	,				
Plumbing System					
Is there a temperature pressure relief valve on the water heater? 🗹 Yes 🗆	□No				
Is there any indication of an active leak? \square Yes \square No Is there any indication of a prior leak? \square Yes \square No					
Water heater location: Garage/MFD 2021					
General condition of the following plumbing fixtures and connections	to annicances:				
Satisfactory Unsatisfactory N/A Dishwasher ☑ □ □	Satisfactory Unsatisfactory N/A Toilets ☑ □ □				
Refrigerator	Sinks				
Washing Machine ☑ ☐	Sump pump				
Water Heater □ □	Main shut off valve ☐ ☐				
Showers/Tubs	All other visible				
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).					
Supplemental Information					
And of Dining Contamy					
X Original to home	Type of pipes (check all that apply) ☑ Copper				
Completely re-piped	☑ copper ☑ PVC/CPVC				
Partially re-piped					
(Provide year and extent of renovation in the comments below)					
	☐ Polybutylene				
	☐ Other (specify)				

Roof (With photos of each roof slope, this section can take the place of the <i>Roof Inspection Form.</i>)						
Predominant Roof Covering material: Metal Tile Roof age (years): 17 Remaining useful life (years): 23 Date of last roofing permit: 05/24/2006 Date of last update: 05/24/2006 If updated (check one):		Secondary Roof Covering material: Roof age (years): Remaining useful life (years): Date of last roofing permit: Date of last update: If updated (check one):	Covering material: Roof age (years): Remaining useful life (years): Date of last roofing permit: Date of last update:			
☑ Full Replacement		☐ Full Replacement	☐ Full Replacement			
☐ Partial Replacement		☐ Partial Replacement	☐ Partial Replacement			
% of replacement		% of replacement	% of replacement			
Overall condition:		Overall condition:	Overall condition:			
☑ Satisfactory		☐ Satisfactory	☐ Satisfactory			
☐ Unsatisfactory (explain below)		☐ Unsatisfactory (explain belo	☐ Unsatisfactory (explain below)			
Any visible signs of damage / deterio	oration?	Any visible signs of damage / de	eterioration?			
Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/Curling Excessive granule loss Exposed asphalt Missing/loose/cracked tabs or tiles Exposed felt Soft spots in decking Visible hail damage Any visible signs of leaks Yes No Attic/underside of decking Yes No Interior ceilings Yes No		Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/Curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks Yes No Attic/underside of decking Yes No Interior ceilings Yes No				
Additional Comments/Observations (use additional pages if needed): All 4-Point Inspection Formsmust be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct.						
Inspector Signature	Keith Curotz Title	License Number	12/05/2023 Date			
mopostor eigrature			2 dito			
Clear2Close Home Inspection	Home Inspector	305.323.7627				
Company Name	License Type	Work Phone				

Special Instructions: This sample *4-Point Inspection Form*includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- Roof: Each slope
- · Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- · Open main electrical panel and interior door
- · Electrical box with the panel off
- Allhazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. Examples include:

- · A general, residential, or building contractor
- · A building code inspector
- A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Formmust be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- · Any visible hazards or deficiencies
- · Any system determined not to be in good working order

Note to All Agents

The writing agent must review each *4-Point Inspection Form* before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

Photos, Additional Comments or Observations

Exterior Photos









Electrical System

Panel Photos











HVAC System







Unit 1

ANY
PART OF DATE (ADDIT)
RESEARCH MANUFACTURING COMPANY
THE ATTENDANCE PRILLA - INSUSPENCE

FOR SIGN ACCOUNTY
THE ATTENDANCE PRILLA - INSUSPENCE

FOR SIGN ACCOUNTY
THE ATTENDANCE PRILLA - INSUSPENCE

FOR SIGN ACCOUNTY
THE ATTENDANCE PRILLA - INSUSPENCE

ATTENDANCE PRILLA - INSUSPENCE

ATTENDANCE PRILLA - INSUSPENCE

ATTENDANCE PRILLA - INSUSPENCE

FOR SIGN ACCOUNTY
THE ATTENDANCE PRILATE REPORT OF THE ATTENDANCE PRILATE PRILAT

NOTICE/AVIS


CULUS SECTION OF FAMILIA THAT ALSO LETTE SECTION OF HOM LISTED SECTION OF HOM ALSO LETTED SECTION OF HOM ANALYSIS OF THE MATERIAL OF ANALYSIS OF THE MATERIAL OF THE MATERIAL





Unit 2






Unit 2


Plumbing System

Water Heater



Under cabinet plumbing & drains





















Plumbing



Roof

Photos of Each Slope

Applied date: May 24, 2006 Status date: May 24, 2006

